

REPORT of SURVEY for REPAIRS.

20687

No. 157 Survey held at London Date 7th Nov^r 1856
 on the B.T. "African" Master Franklin
 Tonnage 174 Built at Shorham When built 1836
 By whom built _____ Owners J. Brown Sold Vide
 Port belonging to Gambia Destined Voyage Letter from M^r. Banner Bo.
with Report on "Pina" Down
 If Surveyed Afloat or in Dry Dock Afloat in the West. I. Dock. Lon 17^o 22' 57"
4m 52 ND 47 Supers 45752

Last Survey, No. 19304 Port London SS. 52 11th R. Claps
 Classified Omitted

REPAIRS At the request of the owners examined this vessel
for Re-Entry of Claps, on examination found the ceiling
generally very defective, in hold and tween decks,
sent notice card to the owners recommending
the same to be efficiently repaired, and on the
7th Inst met the owners and Captⁿ on board and
pointed out what would be necessary to be done,
it being very extensive they declined entering on it,

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Under the circumstances we cannot
recommend this vessel for Re-Entry in the Register
Book.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 14th November 1856

Character assigned Record date of Survey

Charge for attendance £1.1.1

H. J. Boulds

J. F. L. Lighth

© 2019

Lloyd's Register
Foundation

LEV 637-0376