

REPORT of SURVEY for REPAIRS.

20934

No. 232 Survey held at London Date 10th March 1857
 on the Ship "William Ash" Master M. Curson
 Tonnage 253 Built at Sunderland When built 1833
 By whom built _____ Owners Gillett & Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock On the Shore Dry Dock
ND 48 Sides 48 TSD Dp 32

Last Survey, No. 18947 Port Dover Classed SS. 30 C 3 Clap
SS. 30 C 3 SS. 30 C 3 SS. 30 C 3

REPAIRS Remarks: at the request of the Owners, we surveyed this vessel for the 4th A.E. Character and Change of Owners.
 And found some of the sheerstrakes, topsides in way of chain bolts, upper deck clamps on the St. A. side, ceiling in lower hold, and between decks and some of the treenails very defective.
 Sent Notice Card to the Owner on the 12th Inst. recommending the above named defects to be removed and renewed, before she is reported to the Committee for any Character.
 The owners have declined repairing the defects as recommended by us.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

We therefore beg to recommend that her Character be expunged.

The Amount of Fee.....£ : : is received by me,

Special Fee..... 1 4 0

Certificate (if required) : :

Committee's Minute 17th March 1857

Character assigned Record date of Survey

Attendance

H. Boulds.
 J. D. Martin



© 2019

Lloyd's Register Foundation

LON 638-0129