

REPORT of SURVEY for REPAIRS.

20944

Rec 19/3/37

[Signature]

No. 283 Survey held at London Date 7 17 Mar 1857
 on the B¹⁴ Duchess of Northumberland Master
 Tonnage 541 Built at Sunderland When built 1834
 By whom built _____ Owners D. Dunbar & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in the East India Dock

Last Survey, No. 20091 Port London Classed 11 F. 1 S.S. 49

REPAIRS at present, Doublers to sides, and sheer strakes
and drifts of poop and fore castle scraped bright
drifts of poop deck found to be nail sick
and the apron found to be defective it has
been split out but not yet replaced

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>good where seen</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Ym</u> When put on <u>1853</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, _____
 Caulking of Bottom, Deck, & Waterways. _____

In the present state this vessel is not fit to retain the Acheron class and her character in my opinion should be

The Amount of Fee.....£ : : is received by me, suspended until she be repaired -
 Special..... : :
 Certificate (if required) : :

Committee's Minute 20th March 1857

Character assigned "Expense" character

*Notice of removal
 28/8/57*

[Signature: J. H. Ritchie]
 Lloyd's Register
 Foundation