

REPORT of SURVEY for REPAIRS.

20991

Recd 11/4/57
Conf

No. 637 Survey held at London Date 25th March 1857
 on the SS "Empress" Master Newman
 Tonnage 267 Built at Dundee When built 1847
 By whom built 233 Owners Newman
 Port belonging to Scilly Islands Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fore & Aft Dock ways

Last Survey, No. 17183 Port London Classed 7th A1. Claps. Omitted

REPAIRS Remarks: - at the request of owner, we surveyed this vessel with a view of obtaining the H. M. F. Character, and found the topsides round the beam fastenings, some of the sheerstrakes, and bores, defective. We recommended the owner to renew all the defective planking as pointed out by us. He has not complied with our recommendation.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

We are of opinion this vessel in her present condition is not eligible for any Character.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 14th April 1857

Character assigned Record date of Survey

Charge Special
£2.2.4

H. J. Boolds.
Thos. W. Wawn



© 2019

Lloyd's Register Foundation

LON 638-0193