

REPORT of SURVEY for REPAIRS.

21144

No. 332 Survey held at London Date 22nd April 1856
 on the Sp^r "Roman Emperor" Master Scott
 Tonnage 671 Built at Sunderland When built 1848
 By whom built 793 Owners Greenwell
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Mess Gornes dry dock

Last Survey, No. _____ Port _____ Classed 10 A 1

REPAIRS

The yellow metal sheathing stripped off the ship
 hung in shores and caulked under the Copper.
 Yellow metal renewed upon Belt, also 4 Chain bolts in
 Fore Rigging on port side renewed —

Added, 1 pair of vertical knees to Hold beam in
 the wake of the mizen mast.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	In good order
Lower Deck Beams & Fastenings	Good	Keelsons	Good	Sails	and
Planksheers		Clamps and Shelves		Anchors No. of	sufficient
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales		Copper <u>Y M on F</u> When put on <u>now</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good and firm

This Vessel is now in a good and efficient
 state of repair and is eligible in our opinion to remain

Classed 10 A 1

The Amount of Fee.....£ — : — : is received by me,

Special..... 1 : 1 : —

Certificate (if required) : 5 : —

Committee's Minute

185

Character assigned See N^o 21144 annexed

Charge £ 1.1.0
Special



© 2019

Lloyd's Register
 Foundation

LON 638-0337