

## ANNUAL SURVEYS.

21854

No.        Survey held at London Date 25<sup>th</sup> June 1858  
 on the Ship "Water Castle" Master Daniel  
 Tonnage 1064 Built at Sunderland When built 1855  
 By whom built        Owners Messrs Green  
 Port belonging to London Destined Voyage         
 If Surveyed Afloat or in Dry Dock Afloat in the East India Dock

Last Survey, No. 21100 Port of London Classed 13 A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>      </u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>      </u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>where</u>	Boats <u>      </u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>seen</u>	Masts, Yards, &c. <u>      </u>
Lower Deck Beams & Fastenings <u>Firm</u>	Keelsons <u>Good</u>	Sails <u>      </u>
Planksheers <u>      </u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>      </u>
Sheerstrakes <u>Good</u>	Ceiling <u>do</u>	Cables <u>      </u>
Topsides <u>where</u>	Rudder <u>do</u>	Hawsers and Warps <u>      </u>
Wales <u>seen</u>	Copper <u>Yellow Metal</u> When put on <u>1855</u>	Standing & Running Rigging <u>      </u>
Plank (Bottom) and Counter <u>      </u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where true

Caulked from Yellow Metal line to Waterway beam  
and she appears to be in good condition and in our opinion is  
eligible to continue as Classed A1

Committee's Minute 13<sup>th</sup> July 1858Character assigned 13<sup>th</sup> A1

Certificate (if required)

No.        Survey held at        Date        185  
 on the        Master         
 Tonnage        Built at        When built         
 By whom built        Owners         
 Port belonging to        Destined Voyage         
 If Surveyed Afloat or in Dry Dock       

Last Survey, No.        Port of        Classed       

The present Condition of the

Decks <u>      </u>	Treenails <u>      </u>	Windlass and Capstan <u>      </u>
Waterways <u>      </u>	Breasthooks and Stemson <u>      </u>	Pumps <u>      </u>
Comings <u>      </u>	Transoms, Pointers, and Crutches <u>      </u>	Boats <u>      </u>
Upper Deck Beams & Fastenings <u>      </u>	Timbers of the Frame <u>      </u>	Masts, Yards, &c. <u>      </u>
Lower Deck Beams & Fastenings <u>      </u>	Keelsons <u>      </u>	Sails <u>      </u>
Planksheers <u>      </u>	Clamps and Shelves <u>      </u>	Anchors No. of <u>      </u>
Sheerstrakes <u>      </u>	Ceiling <u>      </u>	Cables <u>      </u>
Topsides <u>      </u>	Rudder <u>      </u>	Hawsers and Warps <u>      </u>
Wales <u>      </u>	Copper <u>      </u> When put on <u>      </u>	Standing & Running Rigging <u>      </u>
Plank (Bottom) and Counter <u>      </u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways       Committee's Minute        18  Character assigned       

© 2019

Certificate (if required).

Lloyd's Register  
Foundation

LON640-0054