

23285

REPORT of SURVEY for REPAIRS.

No. 82 Survey held at London Date 3rd 4th & 9th July 1860
on the S. "Candahar" Master Vait
Tonnage 506 Built at Shields When built 1841
642
By whom built _____ Owners Sheldon &
Port belonging to London Destined Voyage Belize
If Surveyed Afloat or in Dry Dock Globe dry dock & Afloat & in Dock

Last Survey, No. 22817 Port London Classed A. 1
39

REPAIRS

Yellow Metal stripped off recaulked from keel to metal line and remetalled on felt. - new caulking where tested found satisfactory -

On the 9th Inst found one ~~old~~ Beam aft side of fore Mast being scapled at port arm, the Beam ^{in old} at after part of fore Hatchway broken - and of the upper Deck Beams found Beam next abap fore Hatch defective at both Ends. Beam 3rd abap fore Hatch defective at Starb^d End and after Beam of after Hatch defective at Starb^d End - left written notice for the said repairs to be done but my recommendations are deferred being complied with as will be seen from owner's note appended

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>1 lb on feet</u> When put on <u>July 1860</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

This vessel requiring repairs as above stated I am unable to report her favorably for continuance on her present class and therefore respectfully leave this case for the Committee's consideration

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 17th July 1860

Character assigned Expense Character

Notice to owner
L^d 17. 7. 60



© 2019

Lloyd's Register
Foundations 0055