

243/2

REPORT of SURVEY for REPAIRS.

No. 323 Survey held at London Date Dec^r 28th 1861
 on the Basque "Free Trader" Master
 Tonnage 359 Built at Cork When built 1847
409
 By whom built _____ Owners Ingledue
 Port belonging to Strickton Destined Voyage _____

If Surveyed Afloat or in Dry Dock Nelson Dry Dock

Last Survey, No. 22742 Port London Classed 11
 59

REPAIRS

I was called upon to examine this vessel to ascertain if she were fit for the Black Diphthong Class -

An examination found the buttocks wormed, the Nelson and Ceiling very defective, and a plank in the larboard Quarter decayed - the treenails in the topsides slack and doubtful -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

The Owner has been apprized of the existing defects and declined to deal with them - In my opinion she is not fit for any class in her present condition -

B. Weymouth

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 :

Certificate (if required) : :

Committee's Minute 11th January 1862

Character assigned Record date of Survey

