

25198

REPORT of SURVEY for REPAIRS.

No. 181 Survey held at London Date 11th & 13th June 1862
on the Ship Percy Master Rankin
Tonnage 919 Built at St John When built 1837
By whom built _____ Owners Richardson
Port belonging to London Destined Voyage Low Hobart Tn
If Surveyed Afloat or in Dry Dock Timber in dry dock

Last Survey, No. 23320 Port London Classed Y A 1
6-60

REPAIRS

The yellow metal sheathing stripped off the bottom
The vessel caulked from keel to metal line and deck
and the bottom resheathed with g in on part felt.

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>✓</u>	Breasthooks and Stemson	<u>✓</u>	Pumps	<u>✓</u>
Comings	<u>✓</u>	Transoms, Pointers, and Crutches	<u>✓</u>	Boats	<u>Good</u>
Upper Deck Beams & Fastenings	<u>✓</u>	Timbers of the Frame	<u>✓</u>	Masts, Yards, &c.	<u>✓</u>
Lower Deck Beams & Fastenings	<u>Where</u>	Keelsons	<u>Where</u>	Sails	<u>Sufficient</u>
Planksheers	<u>✓</u>	Clamps and Shelves	<u>✓</u>	Anchors No. of	<u>✓</u>
Sheerstrakes	<u>✓</u>	Ceiling	<u>✓</u>	Cables	<u>Where</u>
Topsides	<u>✓</u>	Rudder	<u>Seen</u>	Hawsers and Warps	<u>✓</u>
Wales	<u>✓</u>	Copper	<u>Seen</u>	Standing & Running Rigging	<u>Seen</u>
Plank (Bottom) and Counter	<u>Seen</u>	When put on	<u>How done</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tried

This ship appears in good and efficient condition
eligible to remain as classed Y A 1


The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 :

Certificate (if required) : 5 :

Committee's Minute 6th February 18 62

Character assigned Y A 1



© 2019

Lloyd's Register
Foundation

LON 646-0364