

REPORT of SURVEY for REPAIRS.

Change of Owners

25337

Rev 2/4/63
Eun

No. 430 on the

Survey held at

London

Date

26th March

1863

Ship "Chieftain"

Master

W. Porlase

Tonnage

363

Built at

Dumbarton

When built

1837

By whom built

Owners

M. J. Wilson

Port belonging to

Glasgow

Destined Voyage

If Surveyed Afloat or in Dry Dock

Afloat Victoria Docks

Last Survey, No.

25131

Port

London

Classed

12 A 1

REPAIRS

Rest 55-7

63

Cont 62-2

In consequence of the letters of the late owner Mr. McLarty I sealed up the pumps on the 25th Inst at 10.30 A.M. the vessel having then eight inches in the well, I again sounded the pumps on the 26th at 1.15 P.M. and found seventeen and a half inches; the vessel having made only nine and a half inches in twenty six and three quarter hours.

With reference to the sternpost I found no defect in it and am informed by the foreman who had the repairs in hand that he found none, but that some P.S.O

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

The Amount of Fee.....£ / : : is received by me,

Special.....: : :

Certificate (if required) : 5 : -

Committee's Minute

2nd April

1863

Character assigned

Cont 2 1/2



© 2021

Lloyd's Register Foundation

25337. Jan.

sap was trimmed off the inner post to form
a seating for a sternon knee which was added
by the recommendation of Mr Davy and myself

Thos. H. Wain



© 2021

Lloyd's Register
Foundation