

25577

REPORT of SURVEY for REPAIRS.

No. 39 Survey held at London Date July 9th 1863
on the Ship Green Sacket Master Mitchell
Tonnage 1088 Built at St. Johns When built 1860
By whom built _____ Owners Imp^{ty} Fernie &
Port belonging to Liverpool Destined Voyage New Zealand
If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 16731 Port Liverpool Classed 7 A 1
60

REPAIRS

How done, her bottom Caulked and sheathed
with Yellow Metal on Telt. Two Iron knees
renewed to the Hold Beams -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Caulked Yellow Metal Copper on Telt When put on how	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good where seen -
She is now in good and efficient condition, fit
in our opinion to remain as classed 7 A 1.

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 24th July 1863

Character assigned 7 A 1



© 2021

Lloyd's Register
Foundation

LON647-0256