

25623

# REPORT of SURVEY for REPAIRS.

& Re entry

24<sup>th</sup> July

No. 395 on the 13<sup>th</sup> "Rosebud" Master Robinson

Tonnage 903 Built at Arbroath When built 1860

By whom built \_\_\_\_\_ Owners Souther

Port belonging to London Destined Voyage Barcelona

If Surveyed Afloat or in Dry Dock New Crane dock & London Dock

Last Survey, No. 2779 Port Dundee Classed 7 A 1 60

REPAIRS In consequence of damage  
One plank of bottom on Starboard side at the  
back of the second futlocks renewed with Pine  
and the bilges partially retreenailed. Recaulked from  
Wales to Keel and sheathed with zinc  
Masts and rigging renewed

Length 73 - 6/10  
Breadth 20 - 1/10  
Depth 10 - 3/10

## Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	Good
Lower Deck Beams & Fastenings	Good	Ditto Ditto at other places	Good	Sails	Good
Planksheers		Keelsons		Anchors No. of	sufficient
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper <u>Zinc</u> When put on <u>now</u>			

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is now in good condition and is  
eligible in my opinion to remain classed

The Amount of Fee.....£ - : 10: - is received by me,


Special..... 1: 1: -

Certificate (if required) : 2: 6

Committee's Minute 18<sup>th</sup> August 1863

Character assigned 7 A 1

Thos. Wm. Wain



© 2021

Lloyd's Register  
Foundation