

25662

REPORT of SURVEY for REPAIRS.

Rev 26/8/63

No. 274 Survey held at London Date July 16th to Aug 5th 1863
on the Ship "Dover Castle" Master Styles
Tonnage 1002 Built at Sunderland When built 1858
By whom built _____ Owners P. Green &
Port belonging to London Destined Voyage Port Phillip
If Surveyed Afloat or in Dry Dock Green's Dry Dock & E. S. Dock
Last Survey, No. 24229 Port London Classed B. A. 1.

REPAIRS now done.
Yellow metal sheathing stripped off bottom ship hung in shores, recaulked from keel to gunwale, decks partly caulked, windlaps unhung & linings stripped; resheathed with yellow metal on paper.

Present Condition of the		
Decks	<u>good</u>	Treenails <u>good</u>
Waterways	<u>where</u>	Breasthooks and Stemson <u>where</u>
Comings	<u>seen</u>	Transoms, Pointers, and Crutches <u>seen</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings <u>seen</u>
Lower Deck Beams & Fastenings		Ditto Ditto at other places <u>seen</u>
Planksheers		Keelsons
Sheerstrakes		Clamps and Shelves
Topsides		Ceiling
Wales		Rudder <u>on on</u>
Plank (Bottom) and Counter		Copper <u>paper</u> When put on <u>now</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where tested</u>	
	Windlass and Capstan <u>good</u>	
	Pumps <u>+</u>	
	Boats <u>sufficient</u>	
	Masts, Yards, &c.	
	Sails	
	Anchors No. of <u>13. 13. 15. 21</u>	
	Cables <u>good</u>	
	Hawsers and Warps <u>+</u>	
	Standing & Running Rigging <u>sufficient</u>	

The ship is now in good and efficient condition, eligible in my opinion to remain as classed A. 1

The Amount of Fee.....£ _____ is received by me,
Special..... 1 : 1 : 0
Certificate (if required)..... 5 :
Committee's Minute 4th September 1863
Character assigned B. A. 1

second M
LON647-0331
Lloyd's Register Foundation