

25727

REPORT of SURVEY for REPAIRS.

No. 688 on the Ship "Enmore" Survey held at London Date Aug 15th to Sep 17th 1863
Master Kennedy
Tonnage 539 Built at Bristol When built 1838
By whom built _____ Owners Ships Caran Bros
Port belonging to London Destined Voyage West Indies
If Surveyed Afloat or in Dry Dock Bridge Dry Dock & London Dock

Last Survey, No 24553 Port London Classed 10 A. 1.

REPAIRS

How done. An inner waterway added to the upper deck of Green Heart $10\frac{1}{4} \times 13$ bolted with 7/8 Copper bolts, dowelled to each beam. the main pumps renewed and the upper deck partly Caulked -

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	} <u>Good</u>	Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} <u>Good</u>	Timbers of the Frame at the openings		Masts, Yards, &c.	} <u>Good and</u>
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails	
Planksheers		Keelsons	} <u>Good</u>	Anchors No. of	
Sheerstrakes	} <u>Good</u>	Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper	When put on <u>1862</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Good where seen
The ship is in good and efficient Condition, fit in our opinion to remain as classed 10 A. 1.

B. W. Wainwright
Surveyor

The Amount of Fee.....£..... is received by me,

Special.....

Certificate (if required)

Committee's Minute 29 September 1863

Character assigned 10 A. 1.

