

REPORT of SURVEY for REPAIRS.

25740

No. 81 Survey held at London Date Sep^r 25th 18 63
 on the S. Harkaway Master Johnson
 Tonnage 899 Built at Bundee When built 1852
 By whom built _____ Owners Somes Bros.
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Canal dry dock & E. I. Dock

Last Survey, No. 25007 Port London Classed 15 A 1
10.62

REPAIRS

The Main deck between the fore and main hatches renewed and the yellow metal repaired

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>Good &</u>
Lower Deck Beams & Fastenings <u>Good</u>	Ditto Ditto at other places <u>Good</u>	Sails
Planksheers <u>where seen</u>	Keelsons	Anchors No. of <u>sufficient</u>
Sheerstrakes	Clamps and Shelves <u>where seen</u>	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>T & JM</u> When put on <u>1860</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where seen</u>	

This vessel is eligible in my opinion to remain classed A 1

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 9th October 18 63

Character assigned 15 A 1 W&W



© 2021

Lloyd's Register Foundation
 LON647-0409