

ANNUAL SURVEYS.

25812

No. 39 Survey held at London Date Sep^r 28th 18 63
 on the Barge "Mogen" Master Ferguson
 Tonnage 302² 247 Built at Aberdeen When built 1854
 By whom built Owners Messrs Falconer &
 Port belonging to London Destined Voyage Algoa Bay
 If Surveyed Afloat or in Dry Dock Gun Dry Dock

Last Survey, No. 24246 Port of London Classed 9 A 1
 61

The present Condition of the

| | | | | | |
|-------------------------------|--------------------------|--|----------------|----------------------------|--------------------|
| Decks | } <u>good where seen</u> | Treenails | } <u>good</u> | Windlass and Capstan | } <u>good</u> |
| Waterways | | Breasthooks and Stemson | | Pumps | |
| Comings | } <u>firm</u> | Transoms, Pointers, and Crutches | } <u>where</u> | Boats | } <u>and</u> |
| Upper Deck Beams & Fastenings | | Timbers of the Frame | | Masts, Yards, &c. | |
| Lower Deck Beams & Fastenings | } <u>good</u> | Keelsons | } <u>Seen</u> | Sails | } <u>efficient</u> |
| Planksheers | | Clamps and Shelves | | Anchors No. of | |
| Sheerstrakes | } <u>where</u> | Ceiling | } <u>Seen</u> | Cables | } <u>efficient</u> |
| Topsides | | Rudder | | Hawsers and Warps | |
| Wales | } <u>Seen</u> | Copper <u>G.M.</u> When put on <u>1860</u> | } <u>Seen</u> | Standing & Running Rigging | } <u>Seen</u> |
| Plank (Bottom) and Counter | | | | | |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Now done - Metal patched - She is now in good and efficient condition and fit in my opinion to remain as Classed A 1

Committee's Minute 20th November 18 63

Character assigned 9 A 1

Certificate (if required)

No. 170 Survey held at London Date Sep^r 24th 18 63
 on the Ship "Constance" Master J. W. Lodge
 Tonnage 367 Built at Newhaven When built 1858
 By whom built Owners Messrs Cavan & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock

Last Survey, No. 26285 Port of London Classed 13 A 1
 61

The present Condition of the

| | | | | | |
|-------------------------------|--------------------------|--|----------------|----------------------------|--------------------|
| Decks | } <u>good where seen</u> | Treenails | } <u>good</u> | Windlass and Capstan | } <u>good</u> |
| Waterways | | Breasthooks and Stemson | | Pumps | |
| Comings | } <u>firm</u> | Transoms, Pointers, and Crutches | } <u>where</u> | Boats | } <u>and</u> |
| Upper Deck Beams & Fastenings | | Timbers of the Frame | | Masts, Yards, &c. | |
| Lower Deck Beams & Fastenings | } <u>good</u> | Keelsons | } <u>Seen</u> | Sails | } <u>efficient</u> |
| Planksheers | | Clamps and Shelves | | Anchors No. of | |
| Sheerstrakes | } <u>where</u> | Ceiling | } <u>Seen</u> | Cables | } <u>efficient</u> |
| Topsides | | Rudder | | Hawsers and Warps | |
| Wales | } <u>Seen</u> | Copper <u> </u> When put on <u>1861</u> | } <u>Seen</u> | Standing & Running Rigging | } <u>Seen</u> |
| Plank (Bottom) and Counter | | | | | |

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Now done - Copper patched, and the ceiling in the lower hold wedged up with teak wedges - She is now in good condition and fit in our opinion to remain as Classed A 1

Committee's Minute 20th November 18 63

Character assigned 13 A 1

Certificate (if required)

LON 647-0470