

26153

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 68 Survey held at Port Garmouth Date March 31st 18 64
Supp on the Exile Master Munro
 Tonnage 199 Built at Findhorn When built 1864
 By whom built _____ Owners Anderson
 Port belonging to Findhorn Destined Voyage Marseilles
 If Surveyed Afloat or in Dry Dock Fellows dry dock

Mar 20/4/64
 68

Last Survey, No. 2147 Port Aberdeen Classed Y A 1
 2.64

REPAIRS

In consequence of grounding:

Keel fore and aft new of American Elm six planks of flat on port and eight on starboard of Am: Elm and Red Pine - Recaulked from Keel to plank sheers -

Present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>Good & sufficient</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails	
Plank sheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper When put on			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. where tested good

This vessel is now in good condition and is eligible in my opinion to remain classed Y A 1

The Amount of Fee.....£ : 10 : - is received by me,

Also £ 2 - Special..... 1 : 1 : -


Expense Certificate (if required) : 2 : 6

Thos. M. Wain

Committee's Minute 20th May 18 64

Character assigned Y A 1

Revised Damage Report



© 2019

Lloyd's Register Foundation

LOW 648 - 0253