

26993

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 363 Survey held at London Date July 21st 18 65
on the "S. Windward" Master Lulham
Tonnage 620 Built at Sunderland When built 1860
By whom built _____ Owners Fenwick
Port belonging to London Destined Voyage Hobart Town
If Surveyed Afloat or in Dry Dock Union Dock & E. I Dock

Last Survey, No. 25484 Port London Classed 13 A 1
5-63-

REPAIRS

Yellow metal stripped; recaulked from keel to middle line of deck, and re-sheathed with yellow metal over felt.

Condition of the			
Waterways	Good where seen	Treenails	Windlass and Capstan
Comings		Breasthooks and Stemson	Pumps
Upper Deck Beams & Fastenings		Transoms, Pointers, and Crutches	Boats
Lower Deck Beams & Fastenings		Timbers of the Frame at the openings	Masts, Yards, &c. <i>Condition, how ascertained.</i>
Planksheers		Ditto Ditto at other places	Sails
Sheerstrakes		Keelsons	Anchors No. of
Topsides		Clamps and Shelves	Cables
Wales		Ceiling	Hawsers and Warps
Plank (Bottom) and Counter		Rudder	Standing & Running Rigging
General Observations and Opinion,		Copper <i>F. J. M.</i> When put on <i>now</i>	
		Caulking of Bottom, Deck, & Waterways.	Good & sufficient

This vessel is now in good condition and is eligible in my opinion to remain as

The Amount of Fee.....£ : : is received by me,
Special..... 1 : 1 : -
Certificate (if required) : 5 : -

Classed A 1
Thos. McTear

Committee's Minute 18
Character assigned 13 A 1
record ym