

27068

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 198 Survey held at London Date August 1st 1865
on the S. "Crewell" Master H. Durr
Tonnage 1220 Built at Harwich When built 1854
By whom built _____ Owners Phillips
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Greens lower Dock + E. Dock
Last Survey, No. 26377 Port London Classed 12 A 1
64

REPAIRS

Rebuilt from metal line to Plank sheers -

Present Condition of the			
Decks		Treenails	Windlass and Capstan
Waterways		Breasthooks and Stenson	Pumps
Comings		Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	<i>Good where</i>	Ditto Ditto at other places <i>Good</i>	Condition, how ascertained
Plank sheers		Keelsons	Sails
Sheerstrakes	<i>seen</i>	Clamps and Shelves	Anchors No. of
Topsides		Ceiling	Cables
Wales		Rudder	Hawsers and Warps
Plank (Bottom) and Counter		Copper <i>P. & Y. M.</i> When put on <i>1864</i>	Standing & Running Rigging
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	<i>good where tested</i>

*This vessel is eligible in my opinion
to remain classed 12 A 1*
Thos W. Wain

The Amount of Fee.....£ : : is received by me,
Special.....

Certificate (if required) : :

Committee's Minute *31st October 1865*
Inspector assigned *12 A 1*

Why was this
report not sent
up before the 28⁰⁰⁰⁰ 2

at Nov-165 Mlt

I regret this report has been
overlooked in my note book
JWW



© 2021

Lloyd's Register
Foundation