

27070

REPORT of SURVEY for REPAIRS.

Biennial Survey.

No. in Reg. Book. **No.** 12 Survey held at London Date Oct 5th 1865 1865
 on the Ship Pak Wan + Master W. S. Wawn
 Tonnage 795 Built at Sunderland When built 1863.
 By whom built Peverell Owners J. Paton.
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock "Pull head"

Last Survey, No. 26226 Port London Classed Ex² B.S. 14 A. 1.
Iron & Wood Frame, planked 64

REPAIRS

Sighted the yellow metal, found it unwrinkled, and in good condition throughout. Lifted the timbers, and opened her inside at the upper turn of bilge both sides, and as far as could be seen the copper screw pointed bolts, iron ribs, &c. proved in good condition.

Present Condition of the

in good order		or Yellow Metal Bolts		in good order	
Decks	"	Treenails	Screwpointed Copper	Windlass and Capstan	"
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	"
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of <u>2</u>	"
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder <u>efficient</u>	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper <u>Yellow Metal</u> When put on <u>1864</u>	"	Standing & Running Rigging	"
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.		<u>good</u>	

I am of opinion she is entitled to remain as Class'd Ex² B.S. 14 A. 1.

Samuel Phipps

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 3rd November 1865

Character assigned 14 A 1



© 2021

Lloyd's Register Foundation

LN 650-0188

Pak Wan

REPORT OF SURVEY FOR REPAIRS



© 2021

Lloyd's Register
Foundation