

27326

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 297 Survey held at London Date Sept 27<sup>th</sup> Oct 5<sup>th</sup> 1865.  
on the Ship Robert Morrison Master Spinks  
Tonnage 555 610 Built at Sunderland When built 1853.  
By whom built \_\_\_\_\_ Owners Wilson & Co.,  
Port belonging to London Destined Voyage Swan River  
If Surveyed Afloat or in Dry Dock "Lower Globe"

Rev 13/10/65  
C.B.

Last Survey, No. 26339 Port London. Classed 13. A. 1.  
64

REPAIRS

The yellow metal on this vessel, altho' put on in July last year, has been found so bad, that the whole of it has been now taken off, the bottom again caulked, and resheathed with yellow metal on felt up to 19 feet. —

Present Condition of the

Decks	<u>in good order</u>	Treenails	<u>where seen good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained, <u>from the deck</u>	"
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of <u>3</u>	"
sides	"	Ceiling	"	Cables	"
	"	Rudder <u>efficient</u>	"	Hawsers and Warps	"
(Bottom) and Counter	"	Copper <u>Yellow Metal</u> <u>on felt</u> <u>now</u>		Standing & Running Rigging	"
al Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	<u>good</u>		

I am of opinion She is entitled to remain  
as class'd 13. A. 1.  
Samuel Presons

Amount of Fee.....£ \_\_\_\_\_ is received by me,  
Special..... 1 : 1 : — 12/2/66  
Certificate (if required) \_\_\_\_\_

Committee's Minute 13<sup>th</sup> March 18 66

Character assigned \_\_\_\_\_

13<sup>th</sup> March record MM



© 2021

Lloyd's Register  
Foundation

LN650-0367



Robert Morrison



© 2021

Lloyd's Register  
Foundation