

27494

Rev. J. A. 5. 60
Cut

REPAIRS Now done, the Epistles Part Caulked - the Windlass turned out, examined, and found good - the Kulson Cleared, and with the floors, examined, and found good -

Decks
Waterways } *wood*
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings } *wood*
Planksheers
Sheerstrakes } *Do not count them*
Topsides
Wales
Plank (Bottom) and Counter

Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the openings
Ditto Ditto at other places
Keelsons
Clamps and Shelves
Ceiling
Rudder
Copper on Selt
When put on 1863

Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors No. of
Cables
Hawsers and Warps
Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

General Observations and Opinion,
The Owners attention was called to the fact - that the wood sheathing has been on since 1838, but as the keel is said to be perfectly tight, and as the sail sheathing is remarkably well worked, and fastened, he was desirous that the metal and wood sheathing should not be disturbed until next year, when the whole of the yellow metal will have to be renewed, at which period the condition of the caulking of the bottom and the fastenings can be thoroughly examined. Under these circumstances, if it meets with the Committee's approval, I beg to recommend
The Amount of Fee.....£..... is received by me.

The Amount of Fee.....£

is received by me

Special.....

Certificate (if required)

Committee's Minute

Character assigned

1866-1867

© 2021

General Committee

W.A.

Foundation

LOAN 650-0505