

28164

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 219 Survey held at London Date Novr 22nd 18 66
on the Barque Helen Master _____
Tonnage 276 Built at Newport When built 1839
By whom built _____ Owners Wright & Langridge 2y - Not the owners from Ship Register
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Commercial dry dock

Last Survey, No. 24884 Port London Classed Rest^d 56. 8 3/4 12 A 1 8.62
EPAIRS Class. Smithell

Call'd at this Vessel, but the Owners or their
Agents declined having her overhauled for reclaping
Samuel Resours.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 2nd April 18 67

Character assigned Deferred WAS.



© 2019

Lloyd's Register
Foundation

LN 651-0511