

28567

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 327 Survey held at London Date Aug 8th 12th 1867
on the Ship "Duke of Sutherland" Master Loultit
Tonnage 1047 Built at Aberdeen When built 1865
By whom built Smith Owners Loultit & Co.
Port belonging to Wick Destined Voyage _____
If Surveyed Afloat or in Dry Dock Kitchell (Dry Dock & London Dock)

Last Survey, No. 2238 Port Aberdeen Classed GA.I.
REPAIRS now done, 65

The Bottom caulked and re-sheathed with Yellow Metal over Felt -
an anchor stock piece fitted to the roughtree rail on each side amidships -

Present Condition of the

Decks	good	Treenails	good	Windlass and Capstan	
Waterways		Breasthooks and Stenson		Pumps	
Comings	where	Transoms, Pointers, and Crutches	where	Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	seen	Ditto Ditto at other places	seen	Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes	seen	Clamps and Shelves	seen	Anchors No. of <u>3 B. 1 S 2 K.</u>	
Topsides		Ceiling		Cables	
Wales	seen	Rudder	seen	Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>F & Y M</u> When put on <u>now</u>		Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good condition, fit in our opinion to remain as classed GA.I.

The Amount of Fee.....£ : : is received by me,

Special.....

Certificate (if required) : :

Committee's Minute 6th September 1867

Character assigned Good

W. Smith
Lloyd's Register
Foundation
LON 652-0268