

28584

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 412 Survey held at London Date Aug 5th to 7th 1867
on the Ship "Goldstream" Master W. 2. Kennedy
Tonnage 156 Built at M'lmn When built 1849
By whom built _____ Owners Teighe and Co
Port belonging to London Destined Voyage Singapore
If Surveyed Afloat or in Dry Dock Green Up^d dry Dock

Last Survey, No. 26640 Port Low. Classed 12.A.1 (1.65)
(Cont 61. Pys)

REPAIRS Now done

Sighted bottom, the yellow metal stripped, caulked from keel to the metal line and resheathed the bottom with yellow metal on felt.

Hold much lumbered with ballast &c.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons not seen

Clamps and Shelves

Ceiling part seen

Rudder good

Copper on When put on now

Caulking of Bottom, Deck, & Waterways. Good where tested.

Windlass and Capstan

Pumps 2

Boats 5

Masts, Yards, &c. good

Condition, how ascertained inspⁿ and enquiry

Sails

Anchors No. of 3 B. 1 S. 2 K.

Cables

Hawsers and Warps

Standing & Running Rigging

The Amount of Fee.....£ : : is received by me,

Special...../ . / . 0.

Certificate (if required)

Committee's Minute

Character assigned

10th September 1867

Cont 8 Pys

W. 2. Kennedy



© 2021

Lloyd's Register Foundation

LON652-0284