

Annual REPORT of SURVEY for REPAIRS.

28649


No. in Reg. Book. **No.** 907 Survey held at London Date Sept^r 11th 1867
 on the Ship "Surrey" Master J Marshall
 Tonnage 1089 Built at Shields When built 1857
 By whom built Marshall Owners Marshall and
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Blackwall dry Dock and East India St^s

Last Survey, No. 27867 Port London Classed B. A. 1 (11.66)
 REPAIRS None done.

Sighted greater part of bottom (there being about 5ft of water in the Dock) the yellow metal patched, the bottoms of topsides, wales, and deck caulked and overhauled.

Added 8 diagonal pointers of Iron bark, to upper deck beam arms, midships on each side, through bolted to beams shelf, and waterways, also secured to the Deck

Thus



Present Condition of the

Decks	Good where seen	Treenails	Good where seen	Windlass and Capstan	Good and efficient where seen
Waterways		Breasthooks and Stemson		Pumps 2	
Comings		Transoms, Pointers, and Crutches		Boats 5	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c. good	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <u>inspⁿ and rigging</u>	
Planksheers		Keelsons <u>part seen</u>		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B. W.</u>	
Topsides		Ceiling <u>part seen</u>		Cables	
Wales		Rudder <u>Ad good</u>		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>Land & J. M. When put on 1866</u>		Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	<u>good where seen</u>		

She is now in good and efficient Condition and fit in my opinion to remain Classed A. 1.
 Joseph New.

The Amount of Fee.....£ : : is received by me.

Special..... : :

Certificate (if required) : :

Committee's Minute 1st October 1867

Character assigned 13 A 1



© 2021

Lloyd's Register
Foundation

LON652-0331