

29202

REPORT of SURVEY for ~~REPAIRS~~.

No. in Reg. Book, **No.** 38 Survey held at London Date May 19th 1868
 on the B.T. "Salbot" Master _____
 Tonnage 250 Built at Southampton When built 1851
 By whom built 211 Owners Herman
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Migrams dry Dock

Last Survey, No. 28191 Port Lon. Classed 13 (7.62)

Gave the Captⁿ a written account of the requirements of the Second Continuation Rule, which he declined to fulfil; the ship was undergoing a heavy repair viz Renewing the keewails, also the upper deck waterways and plank sheers, &c. &c.

Joseph Allen.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Plank sheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

The Amount of Fee.....£ : : is received by me,
 Special..... : :
 Certificate (if required) : :

Committee's Minute 19th May 1868
 Character assigned Deferred M's



© 2019
 Lloyd's Register
 Foundation
 LON653-0224