

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 873 Survey held at London Date June 22<sup>d</sup> - 26<sup>th</sup> 1868  
 on the Barque Eudora Master Wm Turnbull  
 Tonnage 222 built at Montrose When built 1864  
 By whom built Birnie Owners Pothonier &  
 Port belonging to London Destined Voyage Natal  
 If Surveyed Afloat or in Dry Dock "Fountain" Dry Dock and afloat

Last Survey, No. 28586 Port Lon. Classified 10. A. 1.

## REPAIRS

Chiefly, or wholly from damage. See Report of Survey.

Stripped off the whole of the yellow metal sheathing and caulked up to about fifteen feet. - Caulking also of topsides overhauled. - drifted out a few through bolts from the hold beam clamps. found started, slightly. and treenails abreast the main mast. renewed them, and introduced a few extra through bolts. - Resheathed with yellow metal on fell up to the height of 13 ft 9. -

## Present Condition of the

Decks	good	Treenails	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	firm	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	from the deck
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors	No. of 3
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	Fel 4 1/4" M When put on Now	Standing & Running Rigging	"
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.		good	

She appears in good condition, and is in my opinion entitled to remain as class'd 10. A. 1.

Samuel Mesurier

The Amount of Fee.....£ 1 : - : is received by me.

Special..... 1 : 1 : 5

Certificate (if required) : :

Committee's Minute 3<sup>d</sup> July 1868

Character assigned 10 A 1

record damage repair