

# REPORT of SURVEY for REPAIRS.

29695

No. in Reg. Book. **No.** 345 on the *18<sup>th</sup> "Leylon"* Survey held at *London* Date *Dec<sup>r</sup> 14<sup>th</sup> 1868* *Rec 24/12/68*  
 Tonnage *265* Built at *Jersey* Master *Cameron* When built *1864*  
 By whom built \_\_\_\_\_ Owners *Alexandre &*  
 Port belonging to *Jersey* Destined Voyage *Penang*  
 If Surveyed Afloat or in Dry Dock *Fountain & W. S. Docks*

Last Survey, No. *27899* Port *London* Classed *10 A 1*  
*66*

## REPAIRS

In consequence of damage from stress of weather; two main hatch deck beams renewed with E. S. Oak and one ceiling with African Oak — yellow metal sheathing stripped off, recaulked from keel overall and the yellow metal sheathing renewed on felt — Winch repaired — Windlass stripped examined and found good; in anticipation of the half time survey

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. Condition, how ascertained.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <i>1 1/2</i> When put on <i>now</i>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <i>good where tested</i>	

This vessel is eligible in my opinion to remain as classed *10 A 1*

The Amount of Fee.....£ : 10 : is received by me, *W. W. Wain*

Special..... 2 : 2 : *28/12/68*

Certificate (if required) - : 5 : -

Committee's Minute *29<sup>th</sup> December 1868*

Character assigned *10 A 1* record *W. W. Wain*



© 2019

Lloyd's Register Foundation

LON654 -0023