

30114

Dec 15/5/69

If Surveyed Afloat or in Dry Dock Bull Head Dry dock and Afloat

REPAIRS

Cont. 67-- 4 yrs 12-67.

Stripped Yellow Metal Sheathing renewed the
2nd Strake of deck next waterway on each side from Poop to
Forecastle of Pitch Pine, caulked from keel to middle of wales
metal line, and resheathed bottom with Yellow Metal on
Selt.

Present Condition of the

Decks
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter

Treenails _____
Breasthooks and Stenson _____
Transoms, Pointers, and Crutches _____
Timbers of the Frame at the openings _____
Ditto Ditto at other places _____
Keelsons _____
Clamps and Shelves _____
Ceiling _____
Rudder _____
Copper *For the* _____ *When put on* _____

Windlass and Capstan 2006
Pumps 5
Boats 4
Masts, Yards, &c. 5
Condition, how ascertained See from the deck
Sails Good
Anchors No. of 3
Cables and
Hawsers and Warps Sufficient
Standing & Running Rigging Good

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Look where tested

Is now in good and efficient condition and in
my opinion eligible to remain as classed.

The Amount of Fee.....£ 1 : — :) is received by me,

Special..... 2 : 2 : 1.85

Certificate (if required) : 5 :

Committee's Minute 18th Mar 1869

Character assigned Capt 4 Regt

В. К. Козлов

© 2019

Lloyd's Register
Foundation

Lon654 - 0281