

REPORT of SURVEY for REPAIRS.

30123

No. in Reg. Book. **No.** 346 Survey held at London Date 27th April 21st May 1868
 on the Ship "Polmaise" Master C Butler
 Tonnage 812 built at (Dundee) When built 1853.
 By whom built _____ Owners Campbell
 Port belonging to Glasgow Destined Voyage not known
 If Surveyed Afloat or in Dry Dock Union dry Dock and East India Dock

Last Survey, No. 28199 Port London Classed 14.A.1 (4.67)
 REPAIRS Now done. Cost 67.97s.

Sighted bottom, the yellow metal patched; and on account of the metal being wrinkled, recommended that some of it should be stripped from each bilge, for the purpose of testing the caulking, which was accordingly done, and found to be in good condition.

Renewed the Steam Anchor weighing 10.2.3. and the fore topmast with Red-pine.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>2</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>3</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>by eye and enquiry</u>
Planksheers	Keelsons <u>small pt seen</u>	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B 1 S. 11</u>
Topsides	Ceiling <u>part seen</u>	Cables
Wales	Rudder <u>Ha good</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>and Y.M. When put on 1867</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where tested.</u>	

Good and efficient where seen

She is now in good and efficient condition, and fit in my opinion to remain as Classed. 14.A.1.

The Amount of Fee.....£ : : is received by me. 20/5/69
 Special.....1-1-0
 Certificate (if required) : : : J. Miller.

Committee's Minute 21st May 18 69
 Character assigned Cont 9 A 1



© 2019

Lloyd's Register Foundation

LN654-0288