

30208

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **322** No. Survey held at London Date 15 June 18 69
 on the Ship Robert Henderson Master John Hendry
 Tonnage 52 built at Aberdeen When built 1857
 By whom built Owners Albion S. Comp^y
 Port belonging to Glasgow Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock King and Queen dry dock and Afloat

Last Survey, No. 5280 Port Greenock Classed G.A.1

REPAIRS

Cost: 66 -- 6 yrs.
 of 8-67.

Shipped Yellow Metal Sheathing, garboard beam, one beam kept thereto, together with the hooding ends and butts in bottom caulked. Nails in shores, false keel, secured all fore and aft of American Elm; and the bottom resheathed with Yellow Metal on felt.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Caulking of Bottom, Deck, & Waterways.

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Is now in good and efficient condition and in my opinion eligible to remain as Classed.

The Amount of Fee.....£ : : is received by me,

Special..... / : / : -

Certificate (if required) : : -


Committee's Minute

18 69

Character assigned

Cost 6 12 1

recon 4m 1869



© 2019

Lloyd's Register
Foundation

LON654-0352