

30518

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. *D 9* No. *109* Survey held at *London* Date, first Survey *9th November* Last Survey *11th November 1869*
on the *Brigantine Emma and Agnes* Master *J. Jenkins*
Tonnage *109* built at *Milford* When built *1869, 6 mo.*
By whom built *Lloyd* Owners *Lloyd*
Port belonging to *Milford* Destined Voyage *West Coast of Africa*
If Surveyed Afloat or in Dry Dock *New Crane Dry Dock and West India Docks*
Last Survey, No. *1323* Port *Mil* Classed *7. A. 1.*
6.69

REPAIRS, &c.

The seams of the bottom, to the metal line, were hollow, they have now been flushed with a thread of Oakum. -
The bottom sheathed with Yellow Metal on Felt. -

Present Condition of the

Decks	Good when seen	Treenails	Good when seen	Windlass and Capstan	Good and sufficient
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder <i>Felt and yellow metal</i>		Hawsers and Warps	
Plank (Bottom) and Counter		Caulking of		Standing & Running Rigging	
Engine Room Skylights		Bottom, Deck, & Waterways <i>Good</i>			
Coal Bunker, Openings, Lids, &c.		Scuppers <i>Good</i>	Cargo and Main Hatchways <i>Good</i>		Hatches <i>Good</i>

General Observations and Opinion,

Is in good condition, and in my opinion, fit to remain as classed viz 7. A. 1.

Wm J. Bone

The Amount of Entry Fee.....£ - : - : is received by me,
Special..... : 10 : 0
Certificate (if required) : : :

Committee's Minute *23rd November 1869*

Character assigned *7th A. 1. record Wm J. Bone*