

# REPORT of SURVEY for REPAIRS.

30925

No. in  
Reg. Book.  
386

No.

Survey held at

London

Date, first Survey

1<sup>st</sup> June

Last Survey

23<sup>rd</sup> June 1870

on the

Ship "Durham"

Master

J. Kerr

Tonnage

1206

built at

Pallion

When built

1864

By whom built

Marshall

Owners

G. Marshall

Port belonging to

London

Destined Voyage

Calcutta

If Surveyed Afloat or in Dry Dock

Fletcher's Dry Dock

Last Survey, No.

20275

Port

Lon.

Classed

13 A 1.

5, 69.

REPAIRS, &c.

Bottom caulked from keel to metal line and re-metalled on felt.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Good

Lower Deck Beams & Fastenings

where

Planksheers

where

Sheerstrakes

Topsides

sun.

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Good

Ditto Ditto at other places

where

Keelsons

Clamps and Shells

Ceiling

sun.

Rudder

Copper 4. M. on 4. When put on

Now

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Good and

Condition, how ascertained

Sails

complete

Anchors No. of

Cables

where sun.

Hawsers and Warps

Standing & Running Rigging

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches Good

General Observations and Opinion,

Is now in good and efficient condition, and fit in our opinion to remain as classed - 13 A 1.

The Amount of Entry Fee.....£ - : -

is received by me,

Special..... 1 : 1 : -

Certificate (if required) : 5 :

Committee's Minute

28<sup>th</sup> June

18

Character assigned

13 A 1

record  
MA

J. H. Eastlake.

Samuel Vernon



© 2021

Lloyd's Register Foundation

LN655-0388