

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 192 Survey held at London Date August 31 18 70
 on the S. "Northfleet" Master J. Oates
 Tonnage 837 built at Northfleet When built 1853
 By whom built _____ Owners J. P. Eaton junr
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Bullhead dry dock & London Dock

Last Survey, No. 1301 Port Milford Classed 14 A 1
 Cont 67 9 51.68

REPAIRS

Stripped yellow metal, recaulked from keel to metal line (hung in stow) and remetalled on Felt.

Ballast in the hold

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>F.Y.M.</u> When put on <u>new</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where seen</u>	

This vessel is eligible in my opinion to remain as classed

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 1

Certificate (if required) : 5 : "

Committee's Minute 2nd September 1870

Character assigned Good 9 A 1

Jos. W. H. Wain



© 2021

Lloyd's Register Foundation

LON 656-0026