

REPORT of SURVEY for REPAIRS.

31765

No. in Reg. Book. **No.** Survey held at London Date, first Survey _____ Last Survey July 13th 1871
 on the S. "Saladin" Master J. Rankin
 Tonnage 782 built at Sunderland When built 1851
 By whom built _____ Owners Henderson
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Princes dry dock + E. S. Dock
 Last Survey, No. 30839 Port Lon. Classed 13A1
 REPAIRS, &c. Cont 64 — 9 4.70
 (H.T. 69.)

Stripped; recaulked throughout, and the yellow metal sheathing unadorned on Felt

Present Condition of the

Decks	<i>Good</i> <i>where seen</i>	Treenails	<i>Good</i> <i>where seen</i>	Windlass and Capstan	<i>Good & sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>T & M</u> When put on <u>now</u>		Standing & Running Rigging	
Engine Room Skylights	Caulking of	Cargo and Main Hatchways	Hatches <u>Good.</u>		
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>good where seen</u>	Scuppers			

General Observations and Opinion,

This vessel is eligible in my opinion to remain as classed 13A1

The Amount of Entry Fee.....£ — : — is received by me,

Special..... 1 : 1 : *25/4/71*

Certificate (if required) : 5 : *25/4/71*

Committee's Minute 28th July 18 71

Character assigned Const 9 record 11/1



© 2021

Lloyd's Register Foundation