

REPORT of SURVEY for REPAIRS.

31903

No. in
Reg. Book.

No.

Survey held at London Date, first Survey 10 Augth Last Survey 26 Augth 1871

on the proprio ship 'Armatie' Master Alex^r Boyd

Tonnage 871 built at Amsterdam When built 1867-1 mo

By whom built Pile Owners S. J. Wait

Port belonging to North Shields Destined Voyage Madras

If Surveyed Afloat or in Dry Dock in a dry dock and afloat

Last Survey, No.

31258

Port

Lon.

Classed

16A1

REPAIRS, &c.

9.70

The whole of the sparring and close ceiling from Hold-Beams downwards including the timbers removed. Bottom under metal sheathing driven out for examination.

The frames, floors and all iron work (excepting the beams) chipped and beaten clean, and the parts thus exposed coated with Paint. Cement coating repaired. Iron decks cleaned and painted, and the Telson metal sheathing on bottom patches. Lubber's keel of Pitch Pine.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations and Opinion,

Freemasts

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

I am in good and efficient condition, and in my opinion eligible to remain as classed and to be marked (5.5-71)

The Amount of Entry Fee.....£ — : — is received by me,

Special.....3 : 3

Certificate (if required)

Committee's Minute

Character assigned



© 2021

Lloyd's Register
Foundation