

32308 *

Composite
REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey _____ Last Survey _____ 18 72
 on the "S + Michael Angelo" Master Suckro
 Tonnage 1174 built at Glasgow When built 1865
 By whom built Cornell Owners Sidgett & Son
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. 31028 Port Lon. Classed 16 A 1

REPAIRS, &c.
Stripped and re-sheathed with yellow metal on Felt in August 1871 - The bills for which have been examined

Present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto Ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper <u>I. J. M.</u> When put on <u>Aug. 71</u>	Standing & Running Rigging _____
Engine Room Skylights _____	Caulking of _____	Cargo and Main Hatchways _____
Coal Bunker, Openings, Lids, &c. _____	Bottom, Deck, & Waterways _____	Hatches _____
Scuppers _____		

General Observations and Opinion,
No request was made for survey on this vessel which caused her to be omitted while in dry dock -
Jos W. Brown

The Amount of Entry Fee.....£ : : is received by me,
 Special..... : :
 Certificate (if required) : :

Committee's Minute _____ 18 _____
 Character assigned _____

