

REPORT of SURVEY for REPAIRS.

32621

No. in Reg. Book. 196 No. 13 Survey held at London Date, first Survey 21st Sept Last Survey Oct 16 1870
 on the "Berwickshire" Master W. Holt
 Tonnage 533 built at Sunderland When built 1870
 By whom built Pickersgill Owners G. Trail & Sons
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock London dock & Princes dry dock
 Last Survey, No. 9930 Port Ad. Classed 11 A 8
 870

REPAIRS, &c.

Yellow metal stripped off; recaulked from keel to plank sheers, and the yellow metal renewed on felt — Eight broken bolts in timbers and sides renewed with yellow metal —

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained <u>Sufficient</u>
Plank sheers <u>Good</u>	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Top sides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>F.S.W.</u> When put on <u>new</u>	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>good</u>	
Scuppers	Cargo and Main Hatchways	Hatches <u>good</u>

General Observations and Opinion,

This vessel is eligible in my opinion to remain as classed A 8

Wm. Wain

The Amount of Entry Fee.....£ : : is received by me,

Special..... / : /

Certificate (if required) : 5 :

Committee's Minute 22nd October 1872

Character assigned 11 A 8



© 2021

Lloyd's Register Foundation