

REPORT of SURVEY for REPAIRS.

32889

No. in Reg. Book. **No.** 24 Survey held at London Date, first Survey 22nd Jan^y Last Survey Feb^y 14th 1873
 on the Barque Vanguard Master J. R. Luckie
 Tonnage 645 built at Sunderland When built 1854
 By whom built _____ Owners J. Baker
 Port belonging to London Destined Voyage Japan
 If Surveyed Afloat or in Dry Dock Mill wall dry dock & East India Docks.
 Last Survey, No. 9807 Port Sunderland Classed Consⁿ G. A. I.
 REPAIRS, &c. 13 70 2.70

Stripp'd off the Yellow metal. Hung her in shores.
 Resheath'd with Yellow metal on felk. - Caulk'd up to gunwale.

New hawsepipe on the Starb'd side. New fore rigging of wire
 new breasthook. Extra bolts put in the stem. - Rudder braces
 examin'd and some of the bolts renew'd. New Crainings to the
 Main hatch on lower deck beams. upper deck repaired.

Present Condition of the

Decks	good	Treenails	where seen good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	from the deck "
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of	3 B. 1 S. 2 H "
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder	efficient	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	See & when put on now	Standing & Running Rigging	"
Engine Room Skylights		Caulking of	good		
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	where tested		
Scuppers	good	Cargo and Main Hatchways	good	Hatches	good

General Observations and Opinion,

She is now in good and efficient condition
 and entitled to remain as class'd Consⁿ G. A. I.
 Samuel Presons

The Amount of Entry Fee.....£ : : is received by me,

Special..... 2 : 2 : OK 19/2/73

Certificate (if required) : :

Committee's Minute 21st Feb^y 1873

Character assigned Good

TBM



© 2021

Lloyd's Register
 Foundation

LONG 58 - 0215

Hayward

REPORT OF SURVEY FOR REPAIRS



© 2021

Lloyd's Register
Foundation