

33688

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey April 5th Last Survey May 28th 1873
on the S "Duke of Sutherland" Master Soutitt &
~~304~~ **316** Tonnage 1047 built at Aberdeen When built 1865 - bmo
By whom built _____ Owners Soutitt & Co
Port belonging to Trick Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Princes dry dock & S.W. Dock
Last Survey, No. Sydney Port Null Classed 10 A 1
REPAIRS, &c. HT69 - 872

Recd 3. 6. 73

yellow metal stripped off; recaulked from keel to metal line and resheathed with yellow metal on felt.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places <u>Good</u>	Condition, how ascertained <u>Sufficient</u>
Planksheers <u>Good</u>	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>F & J M</u> When put on <u>now</u>	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>when better good</u>	
Scuppers	Cargo and Main Hatchways	Hatches <u>Good</u>

General Observations and Opinion,

This vessel is now in good condition, and eligible in my opinion to remain as classed.

The Amount of Entry Fee.....£ : : is received by me,

Special..... 2 2 } A.P. 7/4/74

Certificate (if required) : :

Committee's Minute 14th April 1874

Character assigned 10 A 1

DBW Ym 7773

Thos. W. Wain



© 2021

Lloyd's Register Foundation

LON659-0233