

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** 209 on the **"Peterborough"** Survey held at **London** Date, first Survey **8 July** Last Survey **9th July** 18**74**
Master **E. C. Jenkins**
Tonnage **560** built at **Sunderland** When built **1859** 8 mo.
By whom built **Austin** Owners **Hankey**
Port belonging to **London** Destined Voyage
If Surveyed Afloat or in Dry Dock **Nelson Dry Dock**

Last Survey, No. **32797** Port **London** Cont. Lon. June 74. **Classed** 14 9 **Character in Register Book.** **AI** 1. 73.

REPAIRS, OR EXAMINATION AS PER RULE

Bottom sighted -
Yellow metal sheathing patched
were required -

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights Coal Bunker, Openings, Lids, &c.

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper When put on **1872**

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps **2 M. 2 B.**

Boats **4 in No**

Masts, Yards, &c.

Condition, how ascertained Inquiry & Observation

Sails double suit

Anchors No. of **3 B-15. 1 K**

Cables part seen

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways good Hatches good

This vessel is in a good and efficient condition
fit for the conveyance of dry and perishable goods
to and from all parts of the world, and eligible
in my opinion to remain as classed.

The Amount of Entry Fee ... £ ... received by me, }

Special ... £ ... 187

Certificate (if required) ... £ ...

(Travelling Expenses, if any, £ ...)

Committee's Minute **31 July 1874**

Character assigned

T. Shilston.

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register
Foundation