

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No.** 102 on the *Ship Saint Vincent* Survey held at *London* Date, first Survey *9 June* Last Survey *10 June* 18*75*
 Tonnage under Tonnage Deck *775.01* Built at *Sunderland* When built *1865*
 Ditto of Spar Deck, or Awning Deck *116.74* Owners *Dewitt & Moor* Port belonging to *London*
 Ditto of Roop, or Raised Quarter Deck
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage *891.77* Residence
 Crew Space, as per Rule
 Register Tonnage, cut on Beam *891.77* By whom built *Pile* Destined Voyage
 Engine Room
 Reg. Tons as St'mer, cut on Bm. If Surveyed Afloat or in Dry Dock *dry dock*

Length of Poop *68* ft. Ditto, Forecastle *36* ft. Ditto, Raised Quarter Deck
 Last Survey, No. *33885* Port *London*
 REPAIRS, OR EXAMINATION AS PER RULE *pt G.I.B (Enph BS) 24 this* S.S. *Lon 71*

Yellow Metal stripped off. Caulked on keel to funnel and Re Metalled over felt to upper part of Water.

Ships Name
 Tonnage
 Ditto of
 Ditto
 Ditto
 Ditto
 Ditto
 Condition of the
 Deck Beams & Fastenings
 Lower Deck Beams & Fastenings
 Sheersheers
 Sheerstrakes
 Sides
 Les
 (Bottom) and Counter
 Room Skylights
 Observations, Opinion as to Class, &c.
 Treenails
 Breasthooks and Stenson
 Transoms, Pointers, and Crutches
 Timbers of the Frame at the openings
 Ditto Ditto at other places
 Keelsons
 Clamps and Shelves
 Ceiling
 Rudder
 Copper *Y.M.* When put on *June 75*
 Bottom, Deck, & Waterways
 Coal Bunker, Openings, Lids, &c.
 Scuppers
 Cargo and Main Hatchways
 Hatches
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors No. of
 Cables
 Hawser and Warps
 Standing & Running Rigging

This ship appears in good condition and eligible to remain as classed.

The Amount of Entry Fee ... £
 Special ... £
 Certificate (if required) ... £
 (Travelling Expenses, if any, £)
 Committee's Minute *22 June 1875*
 Character assigned
 received by me, *John P. Congdon*
 19.6.1875
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 It is submitted that this vessel should be specially surveyed, and bolts examined as required by Sect 43 of the Composite Rules.
 Lloyd's Register Foundation

Committee's Minute 25th June 1845

Character assigned 12A

Wm 75 Empuyer Enph BS

TDW

Second Minute



© 2021

Lloyd's Register
Foundation