

REPORT of SURVEY for REPAIRS, &c.

33051

(Recd 11-10-75)

No. in Reg. Book. **No.** Survey held at *London* Date, first Survey *Oct 9* 1875 Last Survey *Oct 9* 1875

347 on the *Ship Eliza Shaw (Composite)* Master *J. Shaw*

| | | | |
|------------------------------------|---|---------------------------------|--------------|
| TONNAGE under Tonnage Deck | Built at <i>Glasgow</i> | When built <i>1863</i> | YEAR. MONTH. |
| Ditto of Spar Deck, or Awning Deck | Owners <i>E. Shaw</i> | Port belonging to <i>London</i> | |
| Ditto of Poop, or Raised Qr. Dk. | Residence | | |
| Ditto of Houses on Deck | By whom built <i>Stephen</i> | Destined Voyage | |
| Ditto of Forecastle | If Surveyed Afloat or in Dry Dock <i>Dry Dock</i> | | |
| Gross Tonnage | | | |
| Crew Space, as per Rule | | | |
| Register Tonnage, cut on Beam | | | |
| Engine Room | | | |
| Reg. Tons as St' mer, cut on Bm. | | | |

Length of Poop *ft.* Ditto, Forecastle *ft.* Ditto, Raised Quarter Deck *ft.* Years assigned. *17th* Character in Register Book. *88 Ben 72*

Last Survey, No. *33669* Port *London* Classed *17th* *374*

REPAIRS, OR EXAMINATION AS PER RULE

At the present time the vessel placed in Dry Dock the bottom sighted and yellow Metal Patched.

owing to damage the bowsprit (Iron) has been repaired and doubled at the Knightheads

It appears this vessel has had damage repairs done this last voyage at South America viz. 5 shifts of hood ends in the Iprides, one length of Waterway, 13 Roughen Stanchions of Paroballast.

The Committee sanction has been obtained by the Owners to retain this Material without prejudice to her present class.

Cause of Repairs to be clearly stated.

Present Condition of the Decks

| | | | | |
|----------------------------------|---|-------------|---|-------------------|
| <i>Good</i> | Freemasts <i>Bottom</i> | <i>Good</i> | Windlass and Capstan | |
| Waterways | Breasthooks and Stemson | " | Pumps | |
| Comings | Transoms, Pointers, and Crutches | " | Boats | |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the openings | " | Masts, Yards, &c. | <i>Good</i> |
| Lower Deck Beams & Fastenings | Ditto Ditto at other places | " | Condition, how ascertained | <i>and</i> |
| Planksheers | Keelsons | " | Sails | <i>Sufficient</i> |
| Sheerstrakes | Clamps and Shelves | " | Anchors No. of <i>3 Bns & 1 thick</i> | <i>where</i> |
| Topsides | Ceiling | " | Cables | <i>they</i> |
| Wales | Rudder | " | Hawsers and Warps | <i>could</i> |
| Plank (Bottom) and Counter | Copper <i>Y Metal</i> When put on <i>1874</i> | <i>Good</i> | Standing & Running Rigging | <i>be seen</i> |
| Engine Room Skylights | Caulking of | <i>Good</i> | Cargo and Main Hatchways | <i>Good</i> |
| Coal Bunker, Openings, Lids, &c. | Bottom, Deck, & Waterways | <i>Good</i> | Hatches | <i>Good</i> |
| Scuppers | | | | |

General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair and entitled to remain as classed by the Committee sanction as stated above.

Senhouse Masterdock

The Amount of Entry Fee ... £ : : received by me, *Hurves*
11/10/75 Special ... £ / : : *12.10.1875*
 Certificate (if required) ... £ : :

(Travelling Expenses, if any, £)

Committee's Minute *12th October 1875*

Character assigned *JBW 17. A*

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation