

REPORT of SURVEY for REPAIRS, &c.

36,036

No. in Reg. Book. **No.** Survey held at Sunderland Date, first Survey Dec 14/76 Last Survey Dec 30/76 1876

76 on the Bk Zehlina Master

TONNAGE under Tonnage Deck 443
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 475
 Crew Space, as per Rule
 Register Tonnage, cut on Beam 475
 Engine Room
 Reg. Tons as St' mer, cut on Bm.

Built at Sunderland When built 1860
 Owners J Brodie Port belonging to Sunderland
 Residence
 By whom built Thompson Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry at Port Cargo in.

Length of Poop 1 ft. Ditto, Forecastle 1 ft. Ditto, Raised Quarter Deck 1 ft.
 Last Survey, No. 34321 Port London Classed 14th 1274
 Character in Register Book but see 74 & 75

REPAIRS, OR EXAMINATION AS PER RULE

At the present time owing to damage
 The Yellow Metal stripped off the bottom
 caulked from keel to above the Males & Re Yellow
 Metal on felt to load line.

one Bover Supplied & Testing Certificate produced.

17-1-0 moved to 18-8-3-0 River Near Commission Testing Machine.

M 2761 - Made 18.75 R.W.C.P.T. B 377.

Signed March 31-1876

Signed J. Hartnup.

This Report has been detained owing to the anchor not being
 supplied. I went to the West India Dock to see it this morning & the
 ship has sailed last night Jan'y 18-1877.

Present Condition of the

Decks	Good	Treenails	When seen	Good	Windlass and Capstan
Waterways	✓	Breasthooks and Stenson	✓	✓	Pumps
Comings	✓	Transoms, Pointers, and Crutches	✓	✓	Boats
Upper Deck Beams & Fastenings	✓	Timbers of the Frame at the openings	✓	✓	Masts, Yards, &c.
Lower Deck Beams & Fastenings	✓	Ditto Ditto at other places	✓	✓	Condition, how ascertained
Planksheers	✓	Keelsons	✓	✓	Sails
Sheerstrakes	✓	Clamps and Shelves	✓	✓	Anchors No. of 3 Bm. & 1 Kd.
Topsides	✓	Ceiling	✓	✓	Cables
Wales	✓	Rudder	✓	✓	Hawsers and Warps
Plank (Bottom) and Counter	✓	Copper Metal When put on	✓	✓	Standing & Running Rigging
Engine Room Skylights	✓	on felt to load line	✓	✓	
Coal Bunker, Openings, Lids, &c.	✓	Caulking of	✓	✓	
Scuppers	✓	Bottom, Deck, & Waterways	✓	✓	
Cargo and Main Hatchways	✓		✓	✓	
Hatches	✓		✓	✓	

General Observations, Opinion as to Class, &c.

She is now in an efficient state of
 Repair & respectfully recommends her to remain
 as classed

Survey Fee 3. 3.

Senhouse Martin

The Amount of Entry Fee ... £ ... received by me,

22/1/77 Special ... £ 1 : 1 : 22 Mar 1877

Certificate (if required) ... £ ...

(Travelling Expenses, if any, £ ...)

Committee's Minute 23rd March 1877

Character assigned

Cour 5A

TSW (M) 70

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

LON 662-0066