

# REPORT of SURVEY for REPAIRS, &c.

\* 36,258

No. in Reg. Book. **No.** 197 on the **13<sup>th</sup> "West"** Survey held at **London** Date, first Survey **5 June** Last Survey **7 June** 18**77**

Master

YEAR.

MONTH.

Official Number  
TONNAGE under Tonnage Deck  
Ditto of Spar Deck, or Awning Deck  
Ditto of Poop  
Ditto of Raised Qr. Dk.  
Ditto of Houses on Deck  
Ditto of Forecastle  
Gross Tonnage  
Crew Space, as per Rule  
Register Tonnage, cut on Beam  
Engine Room  
Reg. Tons as St' mer, cut on Bm.

409

Built at **Sunderland** When built **1848**

Owners **Peverill &** Port belonging to **London**

Residence

By whom built

Destined Voyage

If Surveyed Afloat or in Dry Dock

**Duke Shore dry dock**

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

Classed **13** — **8.76**

Last Survey, No. **35697** Port **London**

REPAIRS, OR EXAMINATION AS PER RULE

This Vessel has been surveyed with the view to the removal of the — in the Register Book, also for the entry and Half Line on the At red Characters.

Ceiling has been removed forward and aft in way of the lower timbers, and the frame where exposed there found partially defective and unsatisfactory. And one floor aft very defective.

The Owner has declined to comply with recommendations made for the proper repairs of the vessel at the ports named.

Notice in writing has been sent to Mr. Peverill the Owner, to the effect, that it will be necessary to remove the Ceiling forward and aft as far as may be necessary.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

The Surveyors are requested not to write on or below the space for Committee's Minute.

The Amount of Entry Fee ... ..£

Special ... ..£

Certificate (if required) ... ..£

(Travelling Expenses, if any, £)

Committee's Minute


Character assigned

received by me,

187

**John Congdon**

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

L20662-0166



36258 *Lon*

for either the chocking or renewal of the timbers,  
and the Floor app to be renewed. Also that the  
Survey on the Vessel to be completed before  
she can be submitted as eligible for classification  
in the Register Book.

*Thos Congdon*

*10011*



© 2021

Lloyd's Register  
Foundation