

REPORT of SURVEY for REPAIRS, &c.

36,674
Rec'd in 77

To. in Survey held at London Date, first Survey 8th Oct^r Last Survey 18th Oct^r 1877
 No. in Book. 884 on the Barque 'Mayola' Master _____
 TONNAGE under Tonnage Deck 314 YEAR. MONTH.
 Ditto of Spar Deck, or Avoing Deck _____
 Ditto of Poop _____
 Ditto of Raised Qr. Dk. _____
 Ditto of Houses on Deck _____
 Ditto of Forecastle _____
 Gross Tonnage 345 Residence _____
 Crew Space, as per Rule _____
 Register Tonnage, cut on Beam 334 By whom built _____
 Engine Room _____
 Reg. Tons as S^rmer, cut on Bm. _____
 If Surveyed Afloat or in Dry Dock Pitchiffe dry dock Destined Voyage _____
 Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft.
 Last Survey, No. 36335 Port London Classed 13 A1 6-77
Cont 69 9/77
H.I. 74

REPAIRS, OR EXAMINATION AS PER RULE
 This vessel was docked for examination of the Yellow Metal on the bottom, when it was found to be very much worn and unfit for a voyage.

Inside some Ceiling, where ballast had been removed, appeared to be in an unsatisfactory condition.

It was suggested to the Owner that in view of the Continuation expiring next year, the metal should be ^{now} stripped off and the vessel specially surveyed inside and outside to the height of metal in anticipation of the Restoration of the Rule. This suggestion has been acted upon only so far regards the removal of one strake of Ceiling at about first cuttack heads on both sides: the frame thus exposed is mostly good, but a general re-docking there appears necessary, and a few timbers will probably require renewal. The Owner has

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Openings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations, Opinion as to Class, &c.
 It is submitted that this vessel unless properly repaired, is not entitled to remain classed in the Register Book.

J. Congdon
 J. Hearle

The Amount of Entry Fee ... £ : received by me, 1877
 Special ... £ :
 Certificate (if required) ... £ :

Committee's Minute
 13th November, 1877.
 20th November, 77.
 Character assigned
 Deferred
 with owner's letter
 21.11.77

Surveyor to Lloyd's Register of British and Foreign Shipping.
 © 2021
 Lloyd's Register Foundation
 LON662-0349

36674 Son

declined to continue the survey, or ~~expense~~ enter upon the repairs required. The vessel has been undocked and it is the intention of the owner to offer her for sale.

A written intimation has been sent the owner, to the effect that the vessel, unless submitted to survey and properly repaired, will be reported to the Committee as ineligible to classification in the Register Book.

J. H. Congdon

[Handwritten signature]



© 2021

Lloyd's Register
Foundation