

REPORT

of SURVEY

REPAIRS, &c.

No. in Reg. Book. 303 on the BK Bencan Survey held at London Date, first Survey May 30 1878 Last Survey May 30 1878

TONNAGE under Tonnage Deck 506 Built at Sunderland Master J Myrle

Ditto of Spar Deck, or Avoing Deck 542 Owners T B Walker When built 1869 YEAR. MONTH.

Ditto of Poop 526 Residence Pile Port belonging to London

Ditto of Raised Qr. Dk. 526 By whom built Pile Destined Voyage by SK

Ditto of Houses on Deck 526 Reg. Tons as St'mer, cut on Bm. 526

Ditto of Forecastle 526

Gross Tonnage 542

Crew Space, as per Rule 526

Register Tonnage, cut on Beam 526

Engine Room 526

Reg. Tons as St'mer, cut on Bm. 526

Length of Poop		ft.	Ditto, Forecastle		ft.	Ditto, Raised Quarter Deck		ft.	Years assigned.	Character in Register Book.
Last Survey, No. 36244			Port		London	Classed		1741	577	
								58	573	

REPAIRS, OR EXAMINATION AS PER RULE SS & Half Time

At the present time the repair place
in Dry Dock stages made above the Yellow
Metal and several bolts above the Y Metal
driven out and found very good.

Windlass running and Woodlign stripped
Chain cable hauler from the Locker and ran on
on Deck and examined 270 fathoms

The other requirements for Half Time
Survey were carried last voyage See London
Report 36244 May 1877

Cause of Repairs to be clearly stated.

Present Condition of the

Decks	<i>Good</i>	Treenails	<i>Bolts</i>	<i>Good</i>	Windlass and Capstan	
Waterways	"	Breasthooks and Stemson		"	Pumps	
Comings	"	Transoms, Pointers, and Crutches		"	Boats	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings		"	Masts, Yards, &c.	<i>Good & sufficient</i>
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places		"	Condition, how ascertained	
Planksheers	"	Keelsons		"	Sails	<i>where</i>
Sheerstrakes	"	Clamps and Shelves		"	Anchors	No. of <i>3 No. 12 & 14 lbs. They</i>
Topsides	"	Ceiling		"	Cables	<i>under</i>
Wales	"	Rudder		"	Hawsers and Warps	<i>be</i>
Plank (Bottom) and Counter	"	Copper	When put on <i>1877</i>		Standing & Running Rigging	<i>see</i>
Engine Room Skylights	<i>✓</i>	Caulking of			Cargo and Main Hatchways	<i>Good</i>
Coal Bunker, Openings, Lids, &c.	<i>✓</i>	Bottom, Deck, & Waterways		<i>Good</i>	Hatches	<i>Good</i>
General Observations, Opinion as to Class, &c.		Scuppers		<i>Good</i>		

General Observations, Opinion as to Class, &c.

She is now in good condition and
entitled to remain as before and Martha
SS Son 1878. & HT Son 1878.

Lehmanse Martindale

The Amount of Entry Fee £	:	:	received by me,
25/5/78 Special £	/	/	30 May 1878
Certificate (if required) £	:	:	
(Travelling Expenses, if any, £)			

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

28th, May. 1878.

Character assigned

17A
Vt. J. 78. S. S. 78

© 2021

Lloyd's Register
Foundation

CON663-0033