

REPORT of SURVEY for REPAIRS, &c.

No. 39605

No. in Survey held at
Reg. Book.

297 on the

TONNAGE under Tonnage Deck
Ditto of Spar Deck, or Avoning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage
Crew Space, as per Rule
Register Tonnage, out on Beam
Engine Room
Reg. Tons as St' mer, out on Bm.

Official Number

London

Date, first Survey

(Received at London Office, 16 9 80)

Last Survey

Master

YEAR.

MONTH.

Built at

When built

Owners

Port belonging to

Residence

By whom built

Destined Voyage

If Surveyed Afloat or in Dry Dock

(State Name of Dock)

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

Port

Classed

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Vessel placed in dry block, yellow metal sheathing stripped off, bottom recaulked from keel to gunwale, and retimbered on felt as before; -
Upper fore topsail yard, and main topgallant mast repaired, lower topsail yard, and Forecastle capstan removed, also nine fathoms of 90 fms of 8" Manila. -

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

This vessel is now in good condition and in our opinion eligible to remain as classed. -

The Amount of Entry Fee ... £ ... received by me,

Special ... £ ... 18 80

Certificate (if required)
to be sent as per margin...

(Travelling Expenses, if any, £ ...)

Committee's Minute

Friday, September 17th 1880

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register
Foundation