

39979
Report of Survey for Repairs of Engines and Boilers.

No. 29979

No. in Survey held at London

Date, first Survey

and

Last Survey Dec. 17th 1880

Reg. Book.

297 on the Machinery of the S.S. "Benamain"

(Number of Visits 1)

Year

Tonnage, Gross 381

Built at Aberdeen

When built 1878

Ditto, Net 247

Owners J & A. Davidson

Port belonging to Aberdeen

Year

Diameter of Cylinder 19" x 30" $\frac{3}{4}$

Engines made by Hall Russell & Co.

When made 1878

Year

Length of Stroke 22"

Boilers made by Ditto

When made 1878

Years assigned.

Character in Register Book.

Pressure of Steam 62 lbs.

If Surveyed Afloat or in Dry Dock On hard

Classed

100 A 1
10.80

Registered Horse Power 43

Last Survey No. 28158

Port Iron

Lloyds M.C. 5.78

Particulars of Repairs and Examination Of Tail Shaft in account of damage
Vessel placed on the Hard alongside Union Dock
when it was found that the tail shaft was broken
short off at after end of brass liner, the propeller
being lost. A new steel tail shaft & cast iron pro-
peller has been fitted.

General Observations, Opinion, and Recommendation:— As far as seen this
ship appears eligible to remain as classed.

Entry or Registering Fee ... £ : : :

Survey Fee ... £ 1 : 1 : received by me,

Certificate (if required) ... £ : : 188

(Travelling Expenses, if any, £)

Committee's Minute

Tuesday January, 11th. 1881.

Assigned

No action
to be taken
TBW

W. E. Weirinson

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
Foundation

LON 664-0600

It is submitted that this
vessel is eligible
to remain as
classified

JM

22/2/80



© 2021

Lloyd's Register
Foundation